

**TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)**

- | | |
|--|--|
| 1. Name of the Officer | : Alayna Mariya |
| 2. Period for which the certificate is issued | : 2024-25 |
| 3. Name of the school | : Koppam English Medium School
Karinganad, Vilayur P.O |
| 4. Nature of Defects if any | Permanent RCC Structure |
| a. Foundation | <u>Block I</u> |
| b. Superstructure | 6.10mx6.10mx3.70m - GF 8Nos |
| c. Roof | 6.10mx6.10mx3.70m - FF 8Nos |
| d. Flooring | <u>Block II</u> |
| e. Miscellaneous (Cracks) | 6.00mx5.00mx3.70m - LKG 2Nos |
| | 6.00mx5.00mx3.70m - UKG 3Nos |
| 5. Any major defects noticed which will render the Building unsafe if any manner | : Nil
6.00mx8.00mx3.70m - Play room
3.00mx3.00mx3.70m - Sick room |
| 6. Whether the maintenance works have been done properly | : Yes
3.45mx5.85mx3.75m - Stay room
3.60x5.85x3.75m- Sleeping room |
| 7. Whether the structure is sound or not for conducting | : Yes
3.00mx4.65mx3.50m - Kitchen
2.00mx3.00mx3.50m - W/A
3.00mx2.70mx3.50m - Store |
| | <u>Block III</u> |
| | 6.10mx6.10mx3.70m GF 4Nos, FF 4Nos |
| | 3.60mx6.25mx3.70m GF 2Nos, FF 2Nos
and stair cabin |

Note: 1. The stability of the structure is should be examined also with reference to location, altitude, intensity of wind, exposure to flood, etc.
2. Any additional observation deemed necessary for the certificate, may be furnished separately with the certificate

Certified that the school was inspected by me on 27/05/2024 and found to be fit to conduct classes for the period 2024-25 for the reason stated above.

Place: Vilayur
Date: 27/05/2024

Alayna Mariya
ALAYNA MARIYA
PEN : 901472
ASSISTANT ENGINEER
LID & EW SECTION
VILAYUR GRAMA PANCHAYAT
Engineer